Work Order ID 60974 Page 1 Tuesday, August 03, 2010 9:21:41 AM Item ID: D4019-1 Accept Setup Start **Revision ID:** Item Name: Rib Stop **Start Date:** 8/4/2010 Start Qty: 4.00 Cust Item ID: Required Date: 8/6/2010 **Req'd Qty:** 4.00 Customer: Reference: Run Start Process Plan: Approvals: Tooling: Date: Stop QC: Date: **SPC (Y/N):** Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. **Work Center ID** Description **Run Hours** Code Qty Qty 1 Number Stamp Draw Nbr **Revision Nbr** D4019 C 100 0.00 Large Fab 0.00 Large Fab 1- Cut tube as per dwg D4019 SAO 10-08-04 Disloslos 2- Drill hole as per dwg 3- remove identification marks and deburn 110 QC5- Inspect part completeness to step on W/O 0.00 0.00 Memo Quality Control 120 Identify as per dwg & Stock Location: (1) A 0.00 Packaging 0.00 Memo Packaging

Dart Aerospace	Ltd
----------------	-----

	•									
W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP PROCEDURE CHANGE						Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	,									
Part No	•	PAR #:	Fault Cat	egory:	NCR	: Yes N	lo <b>DQ</b>	<b>A</b> :	Date:	
	R	esolution:	Dispositi	on:	QA:	N/C Clo	sed:			
NCR:			WORK ORE	DER NON-CONFORM	IANCE	(NCR)	1			
DATE	STEP	Description of NC	Corrective Action Section B			— ver		ation	Approval	Approval
DATE	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Section C		Chief Eng	QC Inspector	
										į
				· · · · · · · · · · · · · · · · · · ·						
	1	1					i	ŀ	I	1

## Work Order ID 60974

Tuesday, August 03, 2010 9:21:41 AM



Page 2

Item ID:

D4019-1

Accept

Setup Start



**Revision ID:** 

Item Name: Rib

Required Date: 8/6/2010

8/4/2010

Start Qty: 4.00

**Req'd Qty:** 4.00

QC: \_\_\_\_

Operation

Description

Date:\_\_\_\_\_

Cust Item ID:

Customer:

Reference:

**Start Date:** 

Approvals:

Process Plan: \_\_\_\_\_ Date: \_\_\_\_ Tooling:

**SPC (Y/N):** 

Date:

Date:

Tool # Plan

Code

Run

Accept

Qty

Start

Stop

Reject

Qty!

Sequence ID/ Work Center ID

130

Set Up/ Tool ID

**Run Hours** 

0.00

Reject Number Stamp

Insp.

Quality Control

Memo

QC21- Final Inspection - Work Order Release

0.00

Dart Aerospace Ltd	Dart	<b>Aeros</b>	pace	Ltd
--------------------	------	--------------	------	-----

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
· · · · · · · · · · · · · · · · · · ·									
	i								
							1		
	i						1		
Davi Na			Fault Oat		NCD: Vo	No DC	1.	Deter	
Part No		PAR #:							
		esolution:						Date: _	
NCR:			WORK ORI	DER NON-CONFORM		,n <i>)</i>		·	
DATE	STEP	EP Description of NC	Initial	Corrective Action Section Description	ion B Sigr		ication tion C	Approval Chief Eng	Approval QC Inspector
		Section A	Chief Eng	Chief Eng	Da		aibh C	Criter Eng	QO INSPECTO
1									
•									

## **Picklist Print**

Tuesday, August 03, 2010 9:21:40 AM

Work Order ID: 60974

Parent Item: D4019-1

Parent Item Name: Rib



Start Date: 8/4/2010 Start Qty: 4.00

Required Date: 8/6/2010

Page 1

Required Qty: 4.00

**Comments:** 

IPP RevA: new issue DD 10.01.25 verified by:EC

per dwg revA 10.03.15 verified by:EC DD 10.04.20 verified by:EC


IPP Rev:B as IPP Rev:C as per dwg revC

	DD 10.04.20 VCIII	icu by.EC					}		}				
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M6061T6TS0.750W.06		Purchased	No			100	f	167.1439	4.73	19.91579			÷
6061-T6 SQ Tube .75 x .75							† :			SAD	L	2-08-	-O'4
				Location		Loc	<u>Otv</u>	Loc Code	1		k I		•
				MAT		89.4	6867				i		
				1	14573	22.	1055		1		)		

<b>Location</b>	Loc Qty
MAT	89.46867
114573	22.1055
114640	67.36317
MAT06	77.6752
103069	38.0526
104422	15.5263
16441	4.07
9671	20.0263

Dart A	leros	pace l	Ltd
--------	-------	--------	-----

	•								
W/O:	· · · · · ·								
DATE	DATE STEP PROCEDURE CHANGE By Da						Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						:			
	·		<del>, , , , , , , , , , , , , , , , , , , </del>						
Part No	<u> </u>	PAR #:	Fault Cat	tegory:	_ NCR: Yes	No <b>DQ</b>	:	Date:	
				Disposition: QA: N/C Closed:					<u>.</u>
NCR:			WORK ORI	DER NON-CONFORMA	ANCE (NC	R)		**************************************	
DATE	CTED	Description of NC		on B	Verific	ification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	&   Section		Chief Eng	QC Inspector
·									
								•	
		,							
1	1								



## **Dart Aerospace Ltd**

	-							-					
W/O:		WORK ORDER CHANGES							Approval				
DATE	STEP	PRO	OCEDURE CH	ANGE	E	Зу	Date	aty	Approval QC Inspector				
									Prod Mgr				
								<u> </u>		<u> </u>			
Part No:		PAR #:	Fault Cat	egory:	_ NCR:	Yes N	lo DQA		· · · · · · · · · · · · · · · · · · ·				
	R	esolution:	Dispositi	tion: QA: N/C Closed:					Date:				
NCR:			WORK ORI	DER NON-CONFORM	ANCE (	NCR)							
DATE	STEP	Description of NC	Corrective Action Section			2: 0	Verifica	tion	Approval	Approval			
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	h C	Chief Eng	QC Inspector			
:									· · · · · · · · · · · · · · · · · · ·				
<b>,</b>		1				•	1		1	1			